1594 West North Temple, Suite 1210

INSPECTION REPORT

PO Box 145801

Salt Lake City, Utah 84114-5801 Michael O. Leavitt 801-538-5340 Governor Lowell P. Braxton

801-359-3940 (Fax) 801-538-7223 (TDD) Division Director

Partial: XXX Complete: Exploration: Inspection Date & Time: 2/9/2000 / 8:00a.m.-1:00p.m. Date of Last Inspection: 1/10,13/2000

Mine Name: Star Point Mine County: Carbon Permit Number: ACT/007/006						
Permittee and/or Operator's Name: Plateau Mining Corporation						
Business Address: 847 Northwest Highway 191, Helper, Utah 84526						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Johnny Pappas and Surface Crew						
State Officials(s): Bill Malencik Federal Official(s): None						
Weather Conditions: Partly Cloudy, 40's						
Existing Acreage: Permitted- 9,060 Disturbed- 220 Regraded- Seeded- Bonded-						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/_ Temporary Cessation/_ Bond Forfeiture						
Reclamation (_Phase I/_ Phase II/_ Final Bond Release/_ LiabilityYear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For <u>partial inspections</u> check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1.	DEDMITS CHANGE TRANSEED DENEWAL GALE	EVALUATED	N/A	COMMENTS	NOV/ENF
2.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS		Ц		닏
3.	TOPSOIL	[XX]	닏		Ļļ
3. 4.	HYDROLOGIC BALANCE:	\Box	Ш		ш
	DIVERSIONS	(3/3/)	r 1	(3/3/1	f 3
a. b.		[XX]	Ļļ	[XX]	Ë
υ.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	Ļļ		닏
d.	OTHER SEDIMENT CONTROL MEASURES WATER MONITORING	XX	H	[XX]	<u> </u>
u.	EFFLUENT LIMITATIONS		H		닏
5.	EXPLOSIVES		ĻĻ		<u> </u>
5. 6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[XX]	Щ	<u> </u>	<u> </u>
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		H		<u> </u>
8.	NONCOAL WASTE	[XX] [XX]	<u> </u>	[XX] [XX]	[]
9.	PROTECTION OF FISH, WILDLIFE AND	IVVI	ш	ΙΛΛΙ	11
٦.	RELATED ENVIRONMENTAL VALUES	Гl	r 1	r ı	гэ
10.	SLIDES AND OTHER DAMAGE		<u> </u>	[]	- 1
11.	CONTEMPORANEOUS RECLAMATION	, <u>IAAI</u>	[]	<u> </u>	<u> </u>
12.	BACKFILLING AND GRADING	L J	Н	<u> </u>	
13.	REVEGETATION	[XX]			片
14.	SUBSIDENCE CONTROL		[]	[금
15.	CESSATION OF OPERATIONS	[]		77	
16.	ROADS:	11		1_1	ш
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	[]	[XX]	r i
b.	DRAINAGE CONTROLS		Ħ	[XX]	
17.	OTHER TRANSPORTATION FACILITIES	[XX]	H	[]	7
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[]	Ħ	i i	ㄷ
19.	AVS CHECK (4th Quarter-April, May, June) (date)	- []	Ħ	<u> </u>	<u> </u>
20.	AIR QUALITY PERMIT	ii	Γi	Π	Ħ
21.	BONDING & INSURANCE	ii	ΪĪ	i i	īi

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>4</u>

PERMIT NUMBER: ACT/007/006

DATE OF INSPECTION: 2/9/2000

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS

A partial inspection was performed by the undersigned. Highlights of the inspection are as follows:

SUMMARY

- -Star Point mine is considering moving into the Hiawatha seam. There is four to five million tons of recoverable coal. This move is underway because of the uncertainties at the Willow Creek mine. This proposal is to get started after the first of the year. A complexity is the four foot coal seam. The tentative schedule is to start mining the Hiawatha seam in January, 2000. The mine has a life of four years at one million tons per year. The Hiawatha seam has 2% sulfur and is difficult to blend.
- -New ID signs have been installed at the mine.
- -Pond #8 has been cleaned.
- -The cleaning of Pond #5 is well underway. The material is currently stacked within a portion of the pond. The Star Point track hoe broke down. Mr. Pappas stated if they don't get the hoe repaired he would look to bring a contractor in to finish the work. The clean-out material is currently being stacked on the refuse pile. A portion of the clean out material has been taken to the refuse pile. The balance is still stacked in the refuse pile. Mr. Moosman stated that he would have the material moved by next week.
- -The mine site was covered with about three inches of snow depending on the area. The snow came on Monday, February 7, 2000.
- -The used belt adjacent to the coal storage area was discussed. Mr. Fox stated they would take care of the belt; same was removed.
- -Mr. Cooper, Sunnyside Reclamation and Salvage, talked to mine officials about possibly purchasing the Star Point Mine. This is the same company that was involved with the Sunnyside Mine and many experiences.

2. SIGNS AND MARKERS

New ID signs are now in place.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>4</u>

PERMIT NUMBER: ACT/007/006

DATE OF INSPECTION: 2/9/2000

(Comments are Numbered to Correspond with Topics Listed Above)

Identification signs are in place where public roads interface with the permit boundary. Also, other signs include topsoil and refuse pile signs. Stream buffer zone sign marks the encroachment approved areas on adjacent to streams. The disturbed boundary is marked. The permittee has marked each fuel and fluid tank as to content.

4A. HYDROLOGIC BALANCE: DIVERSIONS

There are approximately sixteen miles of constructed diversions within the disturbed and interfacing undisturbed area. This includes water conveyance systems of over 80 ditches and 32 culverts and berms that control and direct runoff. The diversions are designed and discussed in Section 742.300. In the prior inspection, all diversions were functional and maintenance was suggested on several diversions. This was completed as validated today.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

There are nine sediment ponds and three water impoundments. The sediment ponds provide sediment control for the majority of the disturbed areas. There are four BTCA's. The runoff from these areas are treated and controlled by alternative sediment control measures. The water impoundments are associated with the coal wash plant.

None of the sediment ponds were discharging during the inspection. Ponds 1,2,4,5,8, and 9 contained runoff; the remainder were dry. Pond inspections for the third quarter were on file at the mine site, including last year's annual inspection. As previously mentioned, the cleaning of Pond #5 is well underway. Pond #8 has just been cleaned.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Silt fences provide the sediment control on the BTCA areas. The mine has installed redundant sediment control measures including straw bales, silt fences, sumps, and check dams to retain sediment near the source.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The coal mine waste, as approved by the Division, covers an area of approximately 69 acres. The refuse pile approved design includes outslopes NTE 2:1, a MSHA berm, a sloping pile with positive drainage, diversions designed to meet 6 hr 100 year storm event, and commitment on restricting non-coal waste and combustible materials being stored in the refuse pile.

INSPECTION REPORT

(Continuation sheet)

Page <u>4</u> of <u>4</u>

PERMIT NUMBER: ACT/007/006

DATE OF INSPECTION: 2/9/2000

(Comments are Numbered to Correspond with Topics Listed Above)

8. NONCOAL WASTE

The inspector sent a letter to the permittee on the non-coal waste, together with photos. The company was granted an extension on the submission of a plan until 2/11/99. The company has moved some vehicles to the parking area. Equipment has been marked with red paint indicating salvage, sell, or keep. This project is scheduled to be completed by the end of March.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

All roads, both ancillary and primary, are designed and discussed in the MRP. Most of the roads were muddy.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: <u>Johnny Pappas (Plateau)</u> Henry Austin (OSM)
Given to: <u>Pam Grubaugh-Littig (DOGM)</u> Filed to: <u>Price Field Office</u>

Date: February 9, 2000

Inspector's Signature: Malenae #26

Wm. J. Malencik